Bayou State Inspections Lafayette, LA 70508 337-988-9020



Real Estate Inspection Report



The Grand Am Star 16 5996 Zebulon Road Macon, GA 31210

Bayou State Inspections

Prepared for: VSS-Southern Theatres, LLC 5996 Zebulon Road

Table of Contents

Definitions	2
General Information	2
Photo Log	3
Photo Log	7
Photo Log	12
Photo Log	14
Photo Log	15
Photo Log	18

Bayou State Inspections

Prepared for: VSS-Southern Theatres, LLC 5996 Zebulon Road

Definitions

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection

A Acceptable Functional with no obvious signs of defect.

NP Not Present Item not present or not found.

NI Not Inspected Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at

time of inspection.

M Marginal Item is not fully functional and requires repair or servicing.

D Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

General Information

Property Information

Property Address 5996 Zebulon Road

City Macon State GA Zip 31210

Point of Contact Michelle Duren, Director of Operations 980-621-2546

Contact Name Jack Wagner

Client Information

Client Name VSS-Southern Theatres, LLC

Email jackw@southerntheatres.com

Inspection Company

Inspector Name James Yaeger

Company Name Bayou State Inspections

Inspector Name: James Yaeger

Company Name: **Bayou State Inspections**

Address 103 Granite Creek Bend City Lafavette State LA Zip 70508

Phone **3379889020**

Email **jyaegerlsu@gmail.com**Amount Received **\$9992.00**

Conditions

Others Present Workers & Employees Property Condition Occupied; Changing Out Seating

Estimated Age 21+yrs Entrance Faces North

Inspection Date 5/13/2020 thru 5-19-2020

Start Time 0800 End Time 2240

Electric On **②** Yes **O** No **O** Not Applicable

General Information (Continued)

Gas/Oil On **②** Yes **O** No **O** Not Applicable

Water On **O** Yes **O** No **O** Not Applicable

Temperature 66-87'F Exterior 69'F Interior

Weather Clear & Sunny to Partly Cloudy & Sunny Soil Conditions Dry

Wind Light at 1-6mph

Building Type Theater Gutters Aluminum- Damaged by Storm / Wind

Water Source City How Verified Visual Inspection

Sewage Disposal City How Verified Visual Inspection

Additions/Modifications Yes; Prior Roof Repairs; Currently installing new seating in Theaters

Permits Obtained Not Known How Verified N/A

Photo Log

Photo #1: Elevation photos.





Photo #1: (continued)



Photo #2: Visual Roof Condition Photos after the Weather Event.





Photo #2: (continued)









Photo #2: (continued)







Photo Log



Photo #3: (continued)

















Photo #3: (continued)





















Photo #3: (continued)









Photo #4: Damaged Gutter and exposed Roof System.







Photo Log

Photo #5: Roof Overview Photos.



Photo #6: Water entry at Second Floor Mezzanine Area







Photo #6: (continued)











Photo Log

Photo #7: Water damage and entry inside Theatre



Photo #7: (continued)








Photo Log

Infrared / Visual Images of Roof Scan Infrared / Visual Images of Roof Scan

Photo #7: Infrared and Visual Photos of Roof Scan










Photo #8: Infrared and Visual Photos of Roof Scan








Photo Log

Photo #9: Infrared Thermal Scan Photos



Photo #9: (continued)






Photo #9: (continued)




Photo #10: Infrared Thermal Scan Photos




Photo #10: (continued)

